





## **CRITERIA FOR ASSESSMENT OF TRAINEES**

<u>Job Role</u>: Senior Tungsten Inert Gas Welder (GTAW)

**Qualification Pack**: CSC/Q0213

Sector Skill Council: Capital Goods Skill Council

## **Guidelines for Assessment:**

- 1. Criteria for assessment for each Qualification Pack will be created by the Sector Skill Council. Each Performance Criteria (PC) will be assigned marks proportional to its importance in NOS. SSC will also lay down proportion of marks for Theory and Skills Practical for each PC.
- 2. The assessment for the theory part will be based on knowledge bank of questions created by the SSC.
- 3. Individual assessment agencies will create unique question papers for theory part for each candidate at each examination/training centre (as per assessment criteria below)
- 4. Individual assessment agencies will create unique evaluations for skill practical for every student at each examination/training centre based on this criteria
- 5. To pass the Qualification Pack, every trainee should score a minimum of 70% in every NOS
- 6. In case of successfully passing only certain number of NOS's, the trainee is eligible to take subsequent assessment on the balance NOS's to pass the Qualification Pack.

Assessable Outcomes	Assessment Criteria	Total Marks	Out of	Theory	Practical Skills
CSC/N0213 Manually welding joints using the TIG (GTAW) Process	PC1. work safely at all times, complying with health and safety legislation, regulations and other relevant guidelines	100	2	1	1
	PC2. adhere to procedures or systems in place for health and safety, personal protective equipment (PPE) and other relevant safety regulations for TIG welding operations		2	1	1
	PC3. check the condition of welding leads, gas connection arrangements, earthing arrangements and electrode holder		1	0	1
	PC4. report any faults or potential hazards to appropriate authority		1	0	1
	PC5. interpret weld procedure data sheets specifications		2	1	1
	PC6. select welding machines eg. transformer, inverters (AC/DC), rectifiers and generators, according to the materials and task		2	0	2
	PC7. select proper welding torch and tungsten electrode that meet the job requirement and specification		1	0	1
	PC8. obtain filler wire according to		2	1	1







specifications
PC9. prepare for the TIG welding
process
PC10. prepare the materials and
joint in readiness for welding
PC11. select tungsten electrode by
the colour of the tip according to base
metal, and correct diameter
PC12. select and fit the welding
shielding gases for a range of given
applications
PC13. plan the welding activities
before they start them effectively and
efficiently for achieving specifications
as per WPS
PC14. connect torches and
components  DC15 connect and adjust regulators
PC15. connect and adjust regulators
and flow meters to cylinders PC16. read, set and adjust current
(amperage) as required
PC17. set pre-purge with shielding
gas as required
PC18. prepare tungsten by
sharpening or balling it to desired tip
shape
PC19. set and verify gas flow rates
PC20. prepare and support the joint,
using the appropriate methods
PC21. tack weld the joint at
appropriate intervals, and check the
joint for accuracy before final welding
PC22. obtain clearance from quality
control for weld joint before welding
PC23. match feed and travel speed as
required
PC24. perform TIG welding
operations using appropriate welding
techniques to meet welding procedure
specification requirements
PC25. use correct technique for
starting the arc (using HF (high
frequency) unit, scratching the
electrode on the job material, lifting
the electrode immediately after
touching the job material)
PC26. use correct angle of torch and

2       0       2         2       0       2         3       1       2         3       1       2         2       0       2         2       0       2         2       0       2         2       0       2         2       0       2         3       1       2         1       0       1         2       1       1         3       1       2         1       0       1         2       1       1         3       1       2         2       1       1         2       1       1         2       1       1         2       1       1			
3       1       2         2       1       1         3       1       2         2       0       2         2       0       2         2       0       2         2       0       2         2       0       2         3       1       2         1       0       1         2       1       1         4       1       3         3       1       2	2	0	
2       1       1         3       1       2         2       0       2         2       0       2         2       0       2         2       0       2         2       0       2         2       0       2         1       0       1         2       1       1         3       1       2         3       1       2	2	0	2
3       1       2         3       1       2         2       0       2         2       0       2         2       0       2         2       0       2         3       1       2         1       0       1         2       1       1         4       1       3         3       1       2	3	1	2
3     1     2       2     0     2       2     0     2       2     0     2       2     0     2       3     1     2       1     0     1       2     1     1       3     1     2	2	1	1
2     0     2       2     0     2       2     0     2       2     0     2       3     1     2       1     0     1       2     1     1       3     1     2	3	1	2
2     0     2       2     0     2       2     0     2       3     1     2       1     0     1       2     1     1       4     1     3       3     1     2	3	1	2
2     0     2       2     0     2       3     1     2       1     0     1       2     1     1       4     1     3       3     1     2		0	
2     0     2       2     0     2       3     1     2       1     0     1       2     1     1       4     1     3       3     1     2		0	
2     0     2       3     1     2       2     0     2       1     0     1       2     1     1       4     1     3       3     1     2			
2 0 2  1 0 1  2 1 1  4 1 3  3 1 2	2	0	2
2 0 2  1 0 1  2 1 1  4 1 3  3 1 2	2	0	2
1 0 1 2 1 1 4 1 3 3 1 2			
2 1 1 3 4 1 3 3 1 2	2	0	2
3 1 2	1	0	1
3 1 2		1	1
	4	1	3
2 1 1		1	2
	2	1	1







PC27. weld the joint to the specified quality, dimensions and profile PC28. use manual welding and related equipment, to carry out TIG welding processes PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects PC39. detect surface imperfections
PC28. use manual welding and related equipment, to carry out TIG welding processes PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
related equipment, to carry out TIG welding processes PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
related equipment, to carry out TIG welding processes PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types  PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
PC29. use welding consumables appropriate to the material and application, to include AC current types and DC current types  PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
application, to include AC current types and DC current types  PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
PC30. produce joints of the required quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
quality and of specified dimensional accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
accuracy which achieve a weld quality equivalent to Level B of ISO 5817  PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously)  PC32. produce joints from various materials in different forms  PC33. weld joints in good access situations, in select positions  PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
equivalent to Level B of ISO 5817 PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC31. use both methods to produce the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
the various joints a) with filler wire b) without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
without filler wire (autogenously) PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC32. produce joints from various materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
materials in different forms PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC33. weld joints in good access situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
situations, in select positions PC34. shut down and make safe the welding equipment on completion of the welding activities PC35. make sure that the work area is maintained and left in a safe and tidy condition PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC34. shut down and make safe the welding equipment on completion of the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
the welding activities  PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
PC35. make sure that the work area is maintained and left in a safe and tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
tidy condition  PC36. use appropriate methods and equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
equipment to check the quality, and that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
that all dimensional and geometrical aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
aspects of the weld are to the specification  PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection  PC38. identify various weld defects
PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
PC37. check that the welded joint conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
conforms to the specification, by checking various quality parameters using visual inspection PC38. identify various weld defects
checking various quality parameters using visual inspection PC38. identify various weld defects
using visual inspection PC38. identify various weld defects
PC38. identify various weld defects
3
DC20 dotact surface imperfections
PC39. detect surface imperfections in
and deal with them appropriately
PC40. carry out LPT tests to assess
fine defect open to the surface not
detected by visual inspection (VT)
PC41. assist in preparation for non-
destructive testing of the welds for a
range of tests
PC42. prepare for destructive tests
on weld specimens for select tests

3	1	2
3	1	2
2	1	1
4	1	3
3	1	2
3	1	2
3	1	2
2	0	2
1	0	1
3	1	2
3	1	2
2	0	2
	0	
3	1	2
2	1	1
2	1	1







	PC43. follow the established organisational process for dealing with the welded pieces including handover, storage, safety and security, record keeping, etc.		2	1	1
	PC44. detect equipment malfunctions and deal with them appropriately		1	0	1
	PC45. deal promptly and effectively with problems within their control, and seek help and guidance from the relevant people if they have problems that they cannot resolve		1	0	1
		Total	100	26	74
CSC/N1335 Use basic health and safety practices at	PC1. use protective clothing/equipment for specific tasks and work conditions	100	5	2	3
the workplace	PC2. state the name and location of people responsible for health and safety in the workplace		3	1	2
	PC3. state the names and location of documents that refer to health and safety in the workplace		3	1	2
	PC4. identify job-site hazardous work and state possible causes of risk or accident in the workplace		5	2	3
	PC5. carry out safe working practices while dealing with hazards to ensure the safety of self and others state methods of accident prevention in the work environment of the job role		4	2	2
	PC6. state location of general health and safety equipment in the workplace		3	2	1
	PC7. inspect for faults, set up and safely use steps and ladders in general use		5	2	3
	PC8. work safely in and around trenches, elevated places and confined areas		5	2	3
	PC9. lift heavy objects safely using correct procedures		5	2	3
	PC10. apply good housekeeping practices at all times		4	2	2
	PC11. identify common hazard signs displayed in various areas		5	2	3
	PC12. retrieve and/or point out documents that refer to health and		3	1	2







COUNCIL					
	safety in the workplace				
	PC13. use the various appropriate fire extinguishers on different types of fires correctly		4	1	3
	PC14. demonstrate rescue techniques applied during fire hazard	1	4	1	3
	PC15. demonstrate good		3	1	2
	housekeeping in order to prevent fire hazards				_
	PC16. demonstrate the correct use of		4	1	3
	a fire extinguisher				
	PC17. demonstrate how to free a		4	1	3
	person from electrocution				
	PC18. administer appropriate first aid to victims where required eg. in case of bleeding, burns, choking, electric shock, poisoning etc.		4	1	3
	PC19. demonstrate basic techniques of bandaging		3	1	2
	PC20. respond promptly and appropriately to an accident situation or medical emergency in real or simulated environments		4	1	3
	PC21. perform and organize loss minimization or rescue activity during an accident in real or simulated environments		3	1	2
	PC22. administer first aid to victims in case of a heart attack or cardiac arrest due to electric shock, before the arrival of emergency services in real or simulated cases		3	1	2
	PC23. demonstrate the artificial	1	3	1	2
	respiration and the CPR Process PC24. participate in emergency	1	3	2	1
	procedures			-	'
	PC25. complete a written accident/incident report or dictate a	+	4	1	3
	report to another person, and send report to person responsible				
	PC26. demonstrate correct method to move injured people and others during an emergency		4	1	3
		Total	100	36	64
CSC/N1336 Work effectively with	PC1. accurately receive information and instructions from the supervisor	100	10	3	7
others	and fellow workers, getting				
					36







	Total	100	30	70
avoid conflict				
per procedure to resolve them and				
problems to appropriate authority as		10	3	
disciplined behaviors at the workplace PC10. escalate grievances and		10	3	7
PC9. demonstrate responsible and		10	3	7
professionalism		10	2	7
assertiveness, care and				
and language to convey politeness,				
PC8. use appropriate tone, pitch		10	3	7
while interacting with others at work				
PC7. display active listening skills		10	3	7
working				
PC6. display appropriate communication etiquette while		10	3	
efficiency in carrying out tasks  PC6. display appropriate		10	3	7
to maximize effectiveness and				
PC5. consult with and assist others		10	3	7
and possible				
a positive manner, where required				
assisting others in performing tasks in			J	,
PC4. display helpful behavior by		10	3	7
clearly, at a pace and in a manner that helps them to understand				
PC3. give information to others		10	3	7
confirm its receipt		10	•	
and within agreed timescale and				
to authorized persons who require it				
PC2. accurately pass on information		10	3	7
ciamication where required				
clarification where required				